

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	7369	(brushless adj (dc or (direct adj current))) near motor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 08:34
L2	1387	318/779,799,809.ccis.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 08:35
L3	285154	compressor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 08:35
L4	146832	phase near2 (shift or shifted or shifting or advance or advanced or advancing)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 08:35
L5	2086370	starting or start or (start-up) or startup or started or (start adj up)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 08:36
L6	82	1 and (4 same 5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 08:36
L7	77690	"318"/\$.ccis.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 08:36
L8	49	6 and 7	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 08:36
L9	4	8 and 3	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 09:22
L10	14838	(maximum or max or peak) near torque	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 09:22
L11	22	4 same 5 same 10	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 09:22
L12	4	11 and 2	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/03/21 09:22